## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**


Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- BLURRY OR ILLEGIBLE TEXT
- SKEWED/SLATED IMAGES
- COLORED PHOTOS
- BLACK OR VERY DARK BLACK AND WHITE PHOTOS
- UNDECIPHERABLE GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.


As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.



OF TRAVEL

and the state of t RAILE SYSTEM SPRING LOADED FEED BRESKER BARS FEED LOWER SUPPORT BLADES FIRST STAGE, CUI AWAY DIRECTION LOWER SUPPART PLATE (FIXED) CONCEPT THIS DEVICE SEPARATES PANEL MACHINE POINT ZND STAGE SIDE VEIW FIGURE DEPANELLI ZIUFG CENTER BLADE SEPARATES PANEL AT SCORE LING 6 (SEE FIG.1) STAGE END VEIW EDGE BREAKING 220 SEPARATE PANEL DEVICES

Received from < 248 223 9522 > at 2/7/03 1:50:15 PM [Eastern Standard Time]



4

